

Work Order ID 98367

March-12-13 1:48:42 PM

\*98367\*

Page 1

Item ID: D3929-042

Accept

\*N900040100\*

Setup Start

\*NS1\*

Revision ID:

Item Name: Gusset Assembly

Stop

\*NS2\*

Start Date: 3/15/13 Start Qty: 6.00

\*6\*

Cust Item ID:

Required Date: 3/22/13 Req'd Qty: 6.00

\*6\*

Customer:

Reference:

Approvals:

Process Plan: ML 5

Date: 13-03-14

Tooling:

Date:

Run Start

\*NR1\*

QC:

Date:

SPC (Y/N):

Date:

Stop

\*NR2\*

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr	Revision Nbr								
D3929	A								
100		0.00							
*100*									
Waterjet	Memo	0.00							
FLOW CNC Waterjet	1-Cut as per Dwg D3929								
304 125	Dwg Rev: A								
	Prog Rev: A								
	2-Deburr if necessary								
110	QC2- Inspect parts off machine FAI/FAIB	0.00							
*110*									
QC	Memo	0.00							
Quality Control									

12 0 Ac 13.11.04

12 0 Ac 13.11.04

NCR: Yes / No

DQA: \_\_\_\_\_ Date: \_\_\_\_\_

**WORK ORDER NON-CONFORMANCE / UPDATE**

QA Closed: Date:

Work Order: _____			<b>DISPOSITION</b>			<b>AGAINST DEPARTMENT/PROCESS</b>								
			Rework <input type="checkbox"/>	Skid-tube <input type="checkbox"/>	Crosstube <input type="checkbox"/>	Water Jet <input type="checkbox"/>	Engineering <input type="checkbox"/>							
			Scrap <input type="checkbox"/>	Machining <input type="checkbox"/>	Small Fab <input type="checkbox"/>	Prod. Eng. Coor. <input type="checkbox"/>	Quality <input type="checkbox"/>							
			Use-as-is <input type="checkbox"/>	Thermoforming <input type="checkbox"/>	Finishing <input type="checkbox"/>	Rec/Store/Packaging <input type="checkbox"/>	Other <input type="checkbox"/>							
			Work Order Update <input type="checkbox"/>	Large Fab <input type="checkbox"/>	Composite <input type="checkbox"/>	Supplier <input type="checkbox"/>								
<b>Root Cause</b>	Date	Step	Qty	Description of work order update or Non-conformance		Initial Chief Eng	Action Description	Sign & Date	Verification	QC Inspector				
Doc/Data														
Equip/Tooling														
Operator														
Material														
Setup														
Other														
Process														
Supplier														
Training														
Unapproved														
<b>FAULT CATEGORY</b>														
<b>Landing Gear</b> <input type="checkbox"/> Bending <input type="checkbox"/> Centre Not Concentric to O/S <input type="checkbox"/> Cracks <input type="checkbox"/> Crushed/Crimped <input type="checkbox"/> Cuffs <input type="checkbox"/> Heat Treat <input type="checkbox"/> Inspection Strip in Tube <input type="checkbox"/> Ripples in Bend <input type="checkbox"/> Torque Waves in Extrusion <input type="checkbox"/> Turning Sequence <input type="checkbox"/> Wave/Twist in Tube				<b>General</b> <input type="checkbox"/> Bend <input type="checkbox"/> BOM/Route <input type="checkbox"/> Broken/Damaged <input type="checkbox"/> Burrs <input type="checkbox"/> Contamination <input type="checkbox"/> Countersink <input type="checkbox"/> Cut Too Short <input type="checkbox"/> Drill Holes <input type="checkbox"/> Drawing <input type="checkbox"/> Finish <input type="checkbox"/> Folio			<input type="checkbox"/> Grain <input type="checkbox"/> Hardware <input type="checkbox"/> Inspection Incomplete <input type="checkbox"/> Instructions Incomplete/Unclear <input type="checkbox"/> Maintenance <input type="checkbox"/> Mislabeled <input type="checkbox"/> Misread <input type="checkbox"/> Offset <input type="checkbox"/> Out of Calibration <input type="checkbox"/> Out of Sequence <input type="checkbox"/> Outside Dimensions				<input type="checkbox"/> Ovalized <input type="checkbox"/> Over/Under tolerance <input type="checkbox"/> Part Incorrect <input type="checkbox"/> Part Lost/Missing <input type="checkbox"/> Part Moved <input type="checkbox"/> Positioned Wrong <input type="checkbox"/> Power Loss/Surge		<input type="checkbox"/> Pressure/Forced <input type="checkbox"/> Temperature/Cure <input type="checkbox"/> Weld <input type="checkbox"/> Wrong Stock Pulled	

Work Order ID 98367

March-12-13 1:48:42 PM

\*98367\*

Page 2

Item ID: D3929-042

Accept

\*N900040100\*

Setup

Start

\*NS1\*

Revision ID:

Item Name: Gusset Assembly

Stop

\*NS2\*

Start Date: 3/15/13 Start Qty: 6.00

\*6\*

Cust Item ID:

Required Date: 3/22/13 Req'd Qty: 6.00

\*6\*

Customer:

Reference:

Approvals:

Process Plan:

Date:

Tooling:

Date:

Run

Start

\*NR1\*

QC:

Date:

SPC (Y/N):

Date:

Stop

\*NR2\*

Sequence ID/  
Work Center ID

Operation  
Description

Set Up/  
Run Hours

Tool ID

Tool #

Plan  
Code

Accept  
Qty

Reject  
Qty

Reject  
Number

Insp.  
Stamp

120

QC8- Inspect parts - second check

0.00

DAS  
27  
9-89

\*120\*

QC

Quality Control

13.11.04

140

\*140\*

Large Fab

Large Fab

Memo

0.00

0.00

Weld bushings D3907-1 as per dwg D3929

316L rod batch: M125054

(12)

32 13.11.27

150

QC9- Inspect visual per QSI004- Fusion Welds

0.00

DAS  
9  
9-89

\*150\*

QC

Quality Control

0.00

(12)

13.11.28

NCR: Yes / No

DQA: \_\_\_\_\_ Date: \_\_\_\_\_

**WORK ORDER NON-CONFORMANCE / UPDATE**

QA Closed: \_\_\_\_\_ Date: \_\_\_\_\_

Work Order: _____			<b>DISPOSITION</b>			<b>AGAINST DEPARTMENT/PROCESS</b>					
			Rework <input type="checkbox"/>	Skid-tube <input type="checkbox"/>	Crosstube <input type="checkbox"/>	Water Jet <input type="checkbox"/>	Part No. _____			Engineering <input type="checkbox"/>	
			Scrap <input type="checkbox"/>	Machining <input type="checkbox"/>	Small Fab <input type="checkbox"/>	Prod. Eng. Coor. <input type="checkbox"/>	NCR No. _____			Quality <input type="checkbox"/>	
			Use-as-is <input type="checkbox"/>	Thermoforming <input type="checkbox"/>	Finishing <input type="checkbox"/>	Rec/Store/Packaging <input type="checkbox"/>				Other <input type="checkbox"/>	
			Work Order Update <input type="checkbox"/>	Large Fab <input type="checkbox"/>	Composite <input type="checkbox"/>	Supplier <input type="checkbox"/>					
<b>Root Cause</b>	Date	Step	Qty	Description of work order update or Non-conformance		Initial Chief Eng	Action Description		Sign & Date	Verification	QC Inspector
Doc/Data											
Equip/Tooling											
Operator											
Material											
Setup											
Other											
Process											
Supplier											
Training											
Unapproved											
<b>FAULT CATEGORY</b>											
<b>Landing Gear</b>				<b>General</b>							
				Bending <input type="checkbox"/>	Bend <input type="checkbox"/>	Grain <input type="checkbox"/>	Ovalized <input type="checkbox"/>	Pressure/Forced <input type="checkbox"/>			
Centre Not Concentric to O/S <input type="checkbox"/>				BOM/Route <input type="checkbox"/>	Hardware <input type="checkbox"/>	Over/Under tolerance <input type="checkbox"/>	Temperature/Cure <input type="checkbox"/>				
Cracks <input type="checkbox"/>				Broken/Damaged <input type="checkbox"/>	Inspection Incomplete <input type="checkbox"/>	Part Incorrect <input type="checkbox"/>	Weld <input type="checkbox"/>				
Crushed/Crimped <input type="checkbox"/>				Burrs <input type="checkbox"/>	Instructions Incomplete/Unclear <input type="checkbox"/>	Part Lost/Missing <input type="checkbox"/>	Wrong Stock Pulled <input type="checkbox"/>				
Cuffs <input type="checkbox"/>				Contamination <input type="checkbox"/>	Maintenance <input type="checkbox"/>	Part Moved <input type="checkbox"/>					
Heat Treat <input type="checkbox"/>				Countersink <input type="checkbox"/>	Mislabeled <input type="checkbox"/>	Positioned Wrong <input type="checkbox"/>					
Inspection Strip in Tube <input type="checkbox"/>				Cut Too Short <input type="checkbox"/>	Misread <input type="checkbox"/>	Power Loss/Surge <input type="checkbox"/>	Other <input type="checkbox"/>				
Ripples in Bend <input type="checkbox"/>				Drill Holes <input type="checkbox"/>	Offset <input type="checkbox"/>						
Torque Waves in Extrusion <input type="checkbox"/>				Drawing <input type="checkbox"/>	Out of Calibration <input type="checkbox"/>						
Turning Sequence <input type="checkbox"/>				Finish <input type="checkbox"/>	Out of Sequence <input type="checkbox"/>						
Wave/Twist in Tube <input type="checkbox"/>				Folio <input type="checkbox"/>	Outside Dimensions <input type="checkbox"/>						

Work Order ID 98367

March-12-13 1:48:42 PM

\*98367\*

Page 3

Item ID: D3929-042

Accept

\*N900040100\*

Setup Start

\*NS1\*

Revision ID:

Item Name: Gusset Assembly

Stop

\*NS2\*

Start Date: 3/15/13 Start Qty: 6.00

\*6\*

Cust Item ID:

Required Date: 3/22/13 Req'd Qty: 6.00

\*6\*

Customer:

Reference:

Approvals:

Process Plan:

Date:

Tooling:

Date:

Run Start

\*NR1\*

QC:

Date:

SPC (Y/N):

Date:

Stop

\*NR2\*

Sequence ID/  
Work Center ID

Operation  
Description

Set Up/  
Run Hours

Tool ID

Tool #

Plan  
Code

Accept  
Qty

Reject  
Qty

Reject  
Number

Insp.  
Stamp

160

QC5- Inspect part completeness to step on W/O

0.00

DAS

\*160\*

QC

Quality Control

(12) 13-11-25

9

9-89

170

Identify as per dwg & Stock Location: \_\_\_\_\_

0.00

DAS

\*170\*

Packaging

Packaging

12 43

9-89

13-11-28

180

QC21- Final Inspection - Work Order Release

0.00

13/11/2011

\*180\*

QC

Quality Control

Memo

0.00

MF  
13-11-28

NCR: Yes / No

# **WORK ORDER NON-COMPLIANCE / UPDATE**

DQA: Date:

**QA Closed:** \_\_\_\_\_ **Date:** \_\_\_\_\_

Work Order: _____				DISPOSITION		AGAINST DEPARTMENT/PROCESS					
				Rework <input type="checkbox"/>	Skid-tube <input type="checkbox"/>	Crosstube <input type="checkbox"/>	Water Jet <input type="checkbox"/>	Engineering <input type="checkbox"/>			
				Scrap <input type="checkbox"/>	Machining <input type="checkbox"/>	Small Fab <input type="checkbox"/>	Prod. Eng. Coor. <input type="checkbox"/>	Quality <input type="checkbox"/>			
				Use-as-is <input type="checkbox"/>	Thermoforming <input type="checkbox"/>	Finishing <input type="checkbox"/>	Rec/Store/Packaging <input type="checkbox"/>	Other <input type="checkbox"/>			
				Work Order Update <input type="checkbox"/>	Large Fab <input type="checkbox"/>	Composite <input type="checkbox"/>	Supplier <input type="checkbox"/>				
Root Cause	Date	Step	Qty	Description of work order update or Non-conformance		Initial Chief Eng	Action Description	Sign & Date	Verification	QC Inspector	
Doc/Data											
Equip/Tooling											
Operator											
Material											
Setup											
Other											
Process											
Supplier											
Training											
Unapproved											
FAULT CATEGORY											
Landing Gear				General							
<input type="checkbox"/> Bending <input type="checkbox"/> Centre Not Concentric to O/S <input type="checkbox"/> Cracks <input type="checkbox"/> Crushed/Crimped <input type="checkbox"/> Cuffs <input type="checkbox"/> Heat Treat <input type="checkbox"/> Inspection Strip in Tube <input type="checkbox"/> Ripples in Bend <input type="checkbox"/> Torque Waves in Extrusion <input type="checkbox"/> Turning Sequence <input type="checkbox"/> Wave/Twist in Tube				<input type="checkbox"/> Bend <input type="checkbox"/> BOM/Route <input type="checkbox"/> Broken/Damaged <input type="checkbox"/> Burrs <input type="checkbox"/> Contamination <input type="checkbox"/> Countersink <input type="checkbox"/> Cut Too Short <input type="checkbox"/> Drill Holes <input type="checkbox"/> Drawing <input type="checkbox"/> Finish <input type="checkbox"/> Folio							
				<input type="checkbox"/> Grain <input type="checkbox"/> Hardware <input type="checkbox"/> Inspection Incomplete <input type="checkbox"/> Instructions Incomplete/Unclear <input type="checkbox"/> Maintenance <input type="checkbox"/> Mislabeled <input type="checkbox"/> Misread <input type="checkbox"/> Offset <input type="checkbox"/> Out of Calibration <input type="checkbox"/> Out of Sequence <input type="checkbox"/> Outside Dimensions							
				<input type="checkbox"/> Ovalized <input type="checkbox"/> Over/Under tolerance <input type="checkbox"/> Part Incorrect <input type="checkbox"/> Part Lost/Missing <input type="checkbox"/> Part Moved <input type="checkbox"/> Positioned Wrong <input type="checkbox"/> Power Loss/Surge							
				<input type="checkbox"/> Pressure/Forced <input type="checkbox"/> Temperature/Cure <input type="checkbox"/> Weld <input type="checkbox"/> Wrong Stock Pulled							
				<input type="checkbox"/> Other							

# Picklist Print

March-12-13 1:48:42 PM

Page 1

Work Order ID: 98367

Parent Item: D3929-042

Parent Item Name: Gusset Assembly

Start Date: 3/15/13

Required Date: 3/22/13

Start Qty: 6.00

Required Qty: 6.00

## Comments:

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
---------------------------------	------------------------	---------------	-------------	---------------------	------------------	-----------------	--------------------	----------------	-------------	--------------	---------------	----------------	--------

M304S11GA 304/316 0.125 Sheet		Purchased	No			100	sf	258.0000	0.45	2.8421052		An 13.11.04
----------------------------------	--	-----------	----	--	--	-----	----	----------	------	-----------	--	-------------

Location	Loc Qty	Loc Code
MAT020	258	
122521	66	
24445	192	

D3907-1 Bushing		Manufactured	No			130	Each	92.0000	2	126075 → 5,7		2/24/12 321 13.11.27
--------------------	--	--------------	----	--	--	-----	------	---------	---	--------------	--	----------------------

Location	Loc Qty	Loc Code
WA004	52	
88891	1	
89688	1	
95215	15	
96302	35	
WA007	40	
96746	40	

B106314 x 24

NCR: Yes / No

DQA: \_\_\_\_\_ Date: \_\_\_\_\_

**WORK ORDER NON-CONFORMANCE / UPDATE**

QA Closed: \_\_\_\_\_ Date: \_\_\_\_\_

Work Order: _____			<b>DISPOSITION</b>		<b>AGAINST DEPARTMENT/PROCESS</b>						
			Rework Scrap Use-as-is Work Order Update	Skid-tube Machining Thermoforming Large Fab	Crosstube Small Fab Finishing Composite	Water Jet Prod. Eng. Coor. Rec/Store/Packaging Supplier	Engineering Quality Other				
Part No. _____  NCR No. _____											
<b>Root Cause</b>	Date	Step	Qty	Description of work order update or Non-conformance	Initial Chief Eng	Action Description	Sign & Date	Verification	QC Inspector		
Doc/Data											
Equip/Tooling											
Operator											
Material											
Setup											
Other											
Process											
Supplier											
Training											
Unapproved											
<b>FAULT CATEGORY</b>											
<b>Landing Gear</b> <input type="checkbox"/> Bending <input type="checkbox"/> Centre Not Concentric to O/S <input type="checkbox"/> Cracks <input type="checkbox"/> Crushed/Crimped <input type="checkbox"/> Cuffs <input type="checkbox"/> Heat Treat <input type="checkbox"/> Inspection Strip in Tube <input type="checkbox"/> Ripples in Bend <input type="checkbox"/> Torque Waves in Extrusion <input type="checkbox"/> Turning Sequence <input type="checkbox"/> Wave/Twist in Tube				<b>General</b> <input type="checkbox"/> Bend <input type="checkbox"/> BOM/Route <input type="checkbox"/> Broken/Damaged <input type="checkbox"/> Burrs <input type="checkbox"/> Contamination <input type="checkbox"/> Countersink <input type="checkbox"/> Cut Too Short <input type="checkbox"/> Drill Holes <input type="checkbox"/> Drawing <input type="checkbox"/> Finish <input type="checkbox"/> Folio		<input type="checkbox"/> Grain <input type="checkbox"/> Hardware <input type="checkbox"/> Inspection Incomplete <input type="checkbox"/> Instructions Incomplete/Unclear <input type="checkbox"/> Maintenance <input type="checkbox"/> Mislabeled <input type="checkbox"/> Misread <input type="checkbox"/> Offset <input type="checkbox"/> Out of Calibration <input type="checkbox"/> Out of Sequence <input type="checkbox"/> Outside Dimensions				<input type="checkbox"/> Ovalized <input type="checkbox"/> Over/Under tolerance <input type="checkbox"/> Part Incorrect <input type="checkbox"/> Part Lost/Missing <input type="checkbox"/> Part Moved <input type="checkbox"/> Positioned Wrong <input type="checkbox"/> Power Loss/Surge  <hr/> <hr/> <hr/>	
										<input type="checkbox"/> Pressure/Forced <input type="checkbox"/> Temperature/Cure <input type="checkbox"/> Weld <input type="checkbox"/> Wrong Stock Pulled	
										<input type="checkbox"/> Other	

DART AEROSPACE LTD	Work Order:	98367
Description: Support Gusset	Part Number:	D3929-1
Inspection Dwg: D3929	Rev: A	Page 1 of 1

# FIRST ARTICLE INSPECTION CHECKLIST


## X First Article      Prototype

DAS


Measured by:	<i>Ak</i>	Audited by:	27 9.89	Prototype Approval:	N/A
Date:	13.11.04	Date:	13.11.04	Date:	N/A

Rev	Date	Change	Revised by	Approved
A	09.05.27	New Issue P/O D3929-041/-042	KJ 	

ITEM	QTY	QTY	P/N	DESCRIPTION
1	X	1	D3929-041	GUSSET ASSEMBLY
2	X	1	D3929-042	GUSSET ASSEMBLY
11	2	2	D3907-1	BUSHING
12	1	1	D3929-1	SUPPORT GUSSET



**D3929-041 GUSSET ASSEMBLY**



**D3929-042 GUSSET ASSEMBLY**

SEARCHED

INDEXED

FILED

UNCONTRIBUTED COPY

RELEASER'S ENDMENT

RELEASER'S NOTICE

RELEASER'S ORDER

98363\_MLS

13-03-14

RELEASED  
27/04/12 ML


A	NEW ISSUE	MB	09.04.03
REV.	DESCRIPTION	BY	DATE
DESIGN	<i>AB</i>	DART AEROSPACE LTD	
DRAWN	<i>AB</i>	HAWKESBURY, ONTARIO, CANADA	
CHECKED	<i>AB</i>	DRAWING NO.	
MFG. APPR.	<i>AB</i>	D3929	REV. A
APPROVED	<i>AB</i>	SHEET 1 OF 3	
DE APPR.	<i>AB</i>	TITLE	SCALE
DATE	09.04.03	GUSSET ASSEMBLY NTS	

COPYRIGHT © 2009 BY DART AEROSPACE LTD  
THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS  
NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT  
WRITTEN PERMISSION FROM DART AEROSPACE LTD.


A NOTES:  
 1) MATERIAL: N/A  
 2) FINISH: N/A  
 3) TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NOTED  
 4) UNITS: INCHES UNLESS OTHERWISE NOTED  
 5) BREAK SHARP EDGES: 0.005 TO 0.010 MAX  
 6) IDENTIFICATION: IDENTIFY WITH DART P/N "D3929-04X" USING FINE POINT PERMANENT INK MARKER  
 7) WEIGHT: 0.73 lbs EACH  
 8) WELDING: PER DART QSI 004

8            7            6            5            4            3            2            1

98367



98367

D3929-1 SUPPORT GUSSET

## A NOTES:

- 1) MATERIAL: AISI 304/316 STAINLESS STEEL SHEET PER AMS 5513 OR 5524  
11 GAUGE (0.125 THICK)  
REF. DART SPEC. M304S11GA
- 2) FINISH: NONE
- 3) TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NOTED
- 4) UNITS: INCHES UNLESS OTHERWISE NOTED
- 5) BREAK SHARP EDGES: 0.005 TO 0.010 MAX
- 6) IDENTIFICATION: N/A
- 7) WEIGHT: 0.72 lbs

DESIGN	<i>[Signature]</i>	DART AEROSPACE LTD
DRAWN	<i>[Signature]</i>	HAWKESBURY, ONTARIO, CANADA
CHECKED	<i>[Signature]</i>	DRAWING NO.
MFG. APPR.	<i>[Signature]</i>	D3929
APPROVED	<i>[Signature]</i>	REV. A
DE APPR.	<i>[Signature]</i>	SHEET 3 OF 3
DATE	09.04.03	TITLE
		SCALE
		GUSSET ASSEMBLY
		NTS

COPYRIGHT © 2009 BY DART AEROSPACE LTD  
THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS  
NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT  
WRITTEN PERMISSION FROM DART AEROSPACE LTD.

8 7 6 5 4 3 2 1 0